

Safety checks on board

- Applies to : Onboard researchers and technicians
- To be checked by : Chief Scientist or his/her representative
- Items to be checked :
 - ✓ (In/Outside the ship) When using stairs, be careful of slipping and tripping
 - ✓ (In/Outside the ship) Hold on handrails and let other person pass when crossing on stairs
 - ✓ (In/Outside the ship) Make sure that the stairs and areas around them are neat and clean
 - ✓ (In/Outside the ship) When wearing footwear with shoelaces, check that shoelaces are tied properly
 - ✓ (In/Outside the ship) Do not hurry on board
 - ✓ (In/Outside the ship) To avoid unexpected injury, make sure where you are supposed to go
 - ✓ (In/Outside the ship) **When you have a hangover or poor health condition, you must not engage in research/observation work.**
 - ✓ (In/Outside the ship) Offer help if someone has sleeplessness or emotional ups and downs
 - ✓ (In/Outside the ship) Wear necessary PPE (**safety glasses, helmet, safety shoes, globe, safety belt etc.**)
 - ✓ (Inside the ship) Put on footwear with a tightly covered or strapped heel when leaving your room
 - ✓ (Inside the ship) When using stairs, remove gloves to hold the handrails properly
 - ✓ (Outside the ship) Watch out for protrusions on the deck and obstacles overhead
 - ✓ (Outside the ship) Stay away from the deck when heavy objects are being lifted and/or winches are operational
 - ✓ (Outside the ship) Before starting, check with the responsible person the work content and risks involved